

Fig. 1

Headstock Arrangement for Original Lacote Method for fitting Machine Heads using detachable Keep Plate screwed into Recess in Centre Web

*View On Bottom Surface
Of Headstock*

